	Туре	#	Hits	Search Text	DBs	Time Stamp	Comm	Error Definition	Errors
_	BRS	2	273978	poom	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:29			0
7	BRS	<b>6</b>	45550	flour	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:29			0
3	BRS	L15	L15 4036	1 adj 8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:30			0
4	BRS	L22	41084	steering adj wheel	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:30			0
2	BRS	L29	138633 3	resin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:30			0
9	BRS	<b>L</b> 36	7	15 and 22 and 29	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:31			0
2	BRS	L43	L43 2142	15 and 29	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:31			0
8	BRS	L50	989561	(hand adj grip) or handle or lever	USPAT; US-PGPUB; EPO; 2001/ JPO; DERWENT; IBM TDB 15:32	2001/06/19 15:32			0
6	BRS	L57	159	43 and 50	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:32			0
10	BRS	L64	300	feel near4 wood	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/06/19 15:32			0
11	BRS	171	7	43 and 64	USPAT; US-PGPUB; EPO; 2001/06/19 JPO; DERWENT; IBM TDB 15:32	2001/06/19 15:32			0